W, KEVIN HUGHES CHAIRMAN

HAROLD D. WILLIAMS
LAWRENCE BRENNER
KELLY SPEAKES-BACKMAN
ANNE E. HOSKINS
COMMISSIONERS

STATE OF MARYLAND



ANTHONY MYERS
EXECUTIVE DIRECTOR

LESLIE MOORE ROMINE STAFF COUNSEL

> JANICE M. FLYNN ASSISTANT STAFF COUNSEL

PUBLIC SERVICE COMMISSION

February 13, 2015

Matthew K. Segers Assistant General Counsel Pepco Holdings, Inc. 701 Ninth Street, NW Suite 1100 Washington, D.C. 20068

Re: Case 9374 Staff Data Request No. 1 to Potomac

Electric Power Company AMENDED

Dear Mr. Segers:

In accordance with the agreement made among the parties at yesterday's prehearing conference in the above-referenced case, the Staff of the Public Service Commission hereby amends its Staff Data Request No. 1 to Potomac Electric Power Company ("Pepco"), which was sent to Pepco on February 3rd. The only amendment to Data Request No. 1 is the request to include an engineer from the Carderock Springs community to accompany Staff and PEPCO on the requested site visit and to adjust the suggested dates for that visit. As such, the due date for responses to the other requests for data should remain unchanged.

As we discussed at the prehearing conference, any response that contains confidential or proprietary information should be clearly labeled on each page that contains such information. In accordance with our agreement, for each claimed proprietary or confidential designation, Pepco should state the basis for its claim that the information is confidential or proprietary.

Other provisions regarding Pepco's response that were stated in Staff's February 3, 2015 letter remain unchanged.

Thank you for your cooperation. If you have any questions, please call me at 410-767-8008.

(In a south

Assistant Staff Counsel

cc: Preliminary Service List Case 9374 Ray Brubaker, Engineer, MD PSC

AMENDED

Case No. 9374 Staff Data Request No. 1 to Potomac Electric Power Company

- 1 1. Provide the line diagram with all devices identified for feeder number #15111 to include the Carderock Springs community and the first common device.
- 1-2. Provide the details on the work performed on the feeder under case #9240.
- 1-3. Staff engineers and an engineer from the Carderock Springs community would like to accompany a PEPCO engineer and lineman to see feeder #15111, identify components, measure voltages and measure impedance on the system. We are particularly interested in looking at the lines and devices that serve the houses listed on Table 1 of the April 5, 2013 letter from Dr. Phil Rider and Michal Freedhoff, Ph.D to David Collins, Executive Secretary. According to the complaint, these addresses have experienced fires or other electrical incidents. [Our engineers are available on either Feburary 4, 5, 6 or 9.] Staff will contact PEPCO with scheduling options.
- 1-4. Identify the point for each house where PEPCO's responsibility for wiring and maintenance ends and the homeowner's responsibility begins.
- 1-5. Provide PEPCO's records pertaining to the installation, maintenance, and repairs for all equipment listed in item #1.
- 1-6. Provide copies of the results of all investigations, voltage studies, and incident and outage reports for feeder #15111 for the past 5 years.