

In Autumn 2019 we met with Soltesz and Montgomery National Park and Planning Staff and showed them these first photos from October 27, 2019 showing multiple points of runoff and sediment flowing through the woods and newly graded areas into the creek after a rain storm. Since then there have been repeated violations and massive sediment runoff after every rain.





More photos from October 27, 2019





February 11, 2020





April 13, 2020



April 24, 2020





October 2020





December 4, 2020





December 16, 2020

